

水量確認



結果1



結果2



結果3



結果4



試験結果 1. 内部に正常な機能を阻害する浸水を認められない。
2. 高圧機器に水滴の付着なし。

屋根通気孔

前 面

<p>A-a 正面30°</p>		
<p>A-b 正面45°</p>		
<p>A-c 正面60°</p>		
<p>B-a 左30°</p>		
<p>B-b 左45°</p>		

屋根通気孔

前面

<p>B-c 左60°</p>		
<p>C-a 右30°</p>		
<p>C-b 右45°</p>		
<p>C-c 右60°</p>		

屋根通気孔

側面




屋根通気孔

側面

<p>B-c 左60°</p>		
<p>C-a 右30°</p>		
<p>C-b 右45°</p>		
<p>C-c 右60°</p>		

屋根通気孔

		後面	
A-a 正面30°			
A-b 正面45°			
A-c 正面60°			
B-a 左30°			
B-b 左45°			

屋根通気孔

後面

<p>B-c 左60°</p>		
<p>C-a 右30°</p>		
<p>C-b 右45°</p>		
<p>C-c 右60°</p>		

扉通気孔

前面

<p>A-a 正面30°</p>		
<p>A-b 正面45°</p>		
<p>A-c 正面60°</p>		
<p>B-a 左30°</p>		
<p>B-b 左45°</p>		

扉通気孔

前面

<p>B-c 左60°</p>		
<p>C-a 右30°</p>		
<p>C-b 右45°</p>		
<p>C-c 右60°</p>		

扉通気孔

側面

<p>A-a 正面30°</p>		
<p>A-b 正面45°</p>		
<p>A-c 正面60°</p>		
<p>B-a 左30°</p>		
<p>B-b 左45°</p>		

扉通気孔

側面

<p>B-c 左60°</p>		
<p>C-a 右30°</p>		
<p>C-b 右45°</p>		
<p>C-c 右60°</p>		

扉通気孔

後面

A-a
正面30°



A-b
正面45°



A-c
正面60°



B-a
左30°



B-b
左45°



扉通気孔

後面

<p>B-c 左60°</p>	
<p>C-a 右30°</p>	
<p>C-b 右45°</p>	
<p>C-c 右60°</p>	